

**O/O ESTATE OFFICER, HARYANA URBAN DEVELOPMENT AUTHORITY,
BHIWANI**

To

The Chief Administrator,
HUDA, Sector-6, Panchkula.

Memo No. **3394**

Dated : 21.05.2008

Subject: **Inspection Report.**

Kindly find enclosed herewith inspection report of Industrial Sector-
26 dated 16.05.2008 for information and necessary action please.

**Estate Office,
HUDA, Bhiwani**

**ASSESSMENT FORM TO BE FILLED UP BY THE RESIDENT HUDA WELFARE
ASSOCIATION OF INDUSTRIAL SECTOR- 26, BHIWANI
DATE OF INSPECTION =16.05.2008**

1	Name of RWA.	Bhiwani Industrial Association (Regd.)
2	Registration number, Act under which registered & date of registration.	2785
3	Name & Address, Mobile No., e-mail address of the President and General Secretary.	Sh. Dharambir Nehra, President Mobile No. 9315374522 Sh. Sandeep Gupta, General Secretary Mobile No. 9315312918
4	Assessment out of 10 marks in respect of:	
a)	JE (Civil) for water supply, Sewerage & storm water.	3/10
b)	JE (Electrical) for Street light.	4/10
c)	JE (Horti.) for Parks	0/10
d)	JE (Estate Office) for cleanliness, maintenance of open spaces, sineages, prevention & removal of encroachments.	0/10

Sandeep Singla
(General Secretary) Bhiwani
Industrial Association, Bhiwani

TO BE FILED UP BY THE INSPECTING OFFICER:

<p>Whether the Inspecting Officer agrees with the above Assessment done by RWA? If not, then what is his Assessment and reasons therefore.</p>	<p>I disagree regarding point 4(a) and 4(d). Sewerage problem in sum pockets is due to industrial waste which block sewerage pipe. Payment to the contractor (cleanliness) made only after get NOC from RWA.</p>
--	---

(Shiv Prasad Sharma)
Estate Officer, HUDA, Bhiwani
(Signature of the Inspecting Officer)

